

**DELHI JAL BOARD: GOVT. OF NCT OF DELHI
OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)
ROOM NO. 209, VARUNALAYA PHASE-I
KAROL BAGH, NEW DELHI – 110005
23558264**

No./DJB/EE(RWH/GWC)/2019/283

DATED: 21/2/19

To,

The Principal
Bharat Shakti Public School
J-51, Krishan Vihar, Delhi-86


Subject:-Regarding adequacy of rain water harvesting system at Bharat Shakti Public School, J-51, Krishan Vihar, Delhi-86.

Sir/Madam,

The above said unit has been inspected by Joint Inspection Team on 07.02.2018, constituted by Hon'ble NGT in O.A. No. 217/2016. It was found that One No. RWH pit is existing at site (with one no. old recharge well).

The existing RWH structure is adequate to harvest the roof top run-off for catchment area of above said unit. The RWH structure was found to be functional at the time of inspection.

You are advised to keep the existing RWH system neat & clean & maintain the same periodically.


EE (RWH/GWC)

EE (G W CELL)
DELHI JAL BOARD
VARUNALAYA BHAWAN,
JHANDEWALLAN, N.D.-05